INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2024/4/2	MAKE	AICHI	MODEL	SR121
SERIAL No.	PLATE : 440880		STAMP : NOT FOUND		
HR METER	6553 HR	Odometer	km	YEAR	YR
CHASSIS	MODEL –		No. –		
SHOE	610G		TIRE SIZE		
MAX HIGHT	12.0 m		MAX WEIGHT	250 kg	

ENGINE : MODEL S/N		
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT · MT	No. OF GEARS – GEARS
Transmission	FAIR · Attn	
4WD	4WD · 2WD	
Travel	FAIR · Attn	
Swing	FAIR · Attn	ガタあり SWING: LOOSE
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
BOOM		
No. of Section	3 SECTIONS	
DERRICKING CYL.	FAIR · Attn	
EXTENSION CYL.	FAIR · Attn	

INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
シュー緩みあり TRACK LINKS: WORN		

OUTRIGGERS	X · H	
OUTRIGGERS COND.	FAIR · Attn	
COMMENT		
上部アクセル不良		
ACCELERATOR: MALFUNCTION TO OPERATE AT THE BUCKET		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。