INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/4/3	MAKE	CAT	MODEL	307C
SERIAL	CAT0307CEBAJ01389		STAMP	CAT0307CEBAJ01389	
HR METER	ERROR HR		YEAR	YR	
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	にじみあり OIL OOZING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	(YES)・ NO	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	FAIR ・(Attn)	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR)・ Attn	破れあり TORN
Inside Cover	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C)・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	
Arm Cylinder	(FAIR)・ Attn	
BKT	FAIR ・(Attn)	ピンガタあり PIN: LOOSE
BKT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
両側トラックローラー不良多数あり MANY TRACK ROLLERS: MALFUNCTION			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )		
Lever	LONG ・ (WRIST)		
Multi	(MULTI)・ 2 ・ NO		
ARM-CRANE	YES ・(NO)		
BLADE	YES ・(NO)		
OFFSET	YES ・(NO)		
OFFSET Cylinder	FAIR ・ Attn		
Piping	YES ・(NO)	Breaker only ・ Multi	
COMMENT			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。