

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/3	MAKE	TADANO	MODEL	GR-600N-1
SERIAL No.	PLATE : FD5349	STAMP :		TR600-0349	
HR METER	14563	HR	Odometer	80677	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
No. of DRIVE WHEELS	4	WD	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	Attn	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	
JIB	YES	NO	
JIB TYPE	STD	PWR	
MAIN & SUB WIRE	YES	NO	
HOOK	60t, 25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

COMMENT

左右Rステアリングシリンダー油漏れあり
REAR STEERING CYLINDERS: OIL LEAKING

OUTRIGGERS

OUTRIGGERS	X	H	
OUTRIGGERS COND.	FAIR	Attn	*1

COMMENT

*1 左右F、右R縦シリンダー油漏れあり
*1 REAR RIGHT & FRONT VERTICAL CYLINDERS: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。