

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2024/4/3	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE	
MAKE	TADANO		MODEL	TS-75M-1
SERIAL	239661		STAMP	FK415E-522253
HR METER	UNKNOWN	HR	Odometer	128892 km
YEAR				YR
CHASSIS MODEL	FK415E	No.	522253	TIRE
				7.50R16

ENGINE(CRANE) : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
ENGINE(CHASSIS) : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT · MT	No. OF GEARS
		5 GEARS
Transmission	FAIR · Attn	油漏れあり OIL LEAKING
No. of DRIVE WHEELS	2 WD	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	破れ大 TORN
Inside Cover	FAIR · Attn	剥がれあり PEELED
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · NONE	

CRANE	
WEIGHT	-
HOOK	4.9t, BALL
BOOM	
MAIN BOOM	
BOOM TOTAL	
No. of Section	4 SECTIONS
TOP SHEAVE	YES · NO
JIB	STD · PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
OUTRIGGERS	
OUTRIGGERS	FAIR · Attn F: H-TYPE, R: X-TYPE
FRONT JACK	YES · NO
COMMENT	
ウインチモーター油漏れあり WINCH MOTOR: OIL LEAKING	
起伏シリンダー油漏れあり DERRICKING CYLINDER: OIL LEAKING	
マフラー穴あり MUFFLER: HOLE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。