

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	4/3.	MAKE	TADANO	MODEL	GR-160N-1
SERIAL No.	PLATE : 525952		STAMP : T002-0145		
HR METER	18531	HR	Odometer	196384	km
TIRE SIZE	325/95R24		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn	下周り油漏れあり BOTTOM: OIL LEAKING
Blow-By	FAIR <input checked="" type="radio"/> Attn	<input checked="" type="radio"/> A LITTLE <input type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	黒煙あり BLACK FUMES
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	破れあり HUGE CUTS
Inside Cover	FAIR <input checked="" type="radio"/> Attn	内張りカバー剥がれあり PEELED
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C <input type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn にじみあり OIL OOZING
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn
JIB	<input checked="" type="radio"/> YES <input type="radio"/> NO
JIB TYPE	<input checked="" type="radio"/> STD <input type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES <input type="radio"/> NO
HOOK	16t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X <input checked="" type="radio"/> H
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn *1
<b>COMMENT</b>	
旋回ロータリーにじみあり SWING ROTARY: OIL OOZING	
*1 左右F、左R縦シリンダーにじみあり	
*1 REAR LEFT & FRONT VERTICAL CYLINDERS: OIL OOZING	
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。