

INSPECTION SHEET 検品書
TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2024/4/3	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE		
MAKE	KATO		MODEL	NK-75M-V	
SERIAL	3010811		STAMP	UNREADABLE	
HR METER	UNKNOWN	HR	Odometer	179739	km
YEAR					YR
CHASSIS MODEL	No. UNREADABLE			TIRE	7.50R16

ENGINE(CRANE) : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
ENGINE(CHASSIS) : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	オイルパンにじみあり OIL PAN: OIL OOZING
Blow-By	FAIR · <input checked="" type="radio"/> Attn	A LITTLE · <input checked="" type="radio"/> MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT · <input checked="" type="radio"/> MT	No. OF GEARS 5 GEARS
Transmission	<input checked="" type="radio"/> FAIR · Attn	
No. of DRIVE WHEELS	2 WD	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUT
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · NONE	

CRANE	
WEIGHT	-
HOOK	4.9t, BALL
BOOM	
MAIN BOOM	
BOOM TOTAL	
No. of Section	4 SECTIONS
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	STD · PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
COMMENT	
OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> FAIR · Attn H-TYPE
FRONT JACK	<input checked="" type="radio"/> YES · NO
COMMENT	
カウンターウエイトカバー傷あり COUNTER WEIGHT COVER: SCRATCHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。