

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/4/3	MAKE	TCM	MODEL	FD100-2
SERIAL	30U00110			STAMP	138800110
HR METER	UNKNOWN	HR	Odometer	-	km
CAB/CNP	CAB / <u>CNP</u> / NONE			TIRE SIZE	9.00-20
MAX LIFTING HEIGHT	3.0	m	<u>VIEW</u>	MONO	FORK LENGTH
FORK SPEC	サイドシフト付 W/SIDE-SHIFT				

ENGINE : MODEL	S/N
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> · DD
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
FOOT BRAKE	<u>FAIR</u> · Attn
PARKING BRAKE	FAIR · <u>Attn</u> 不良 MALFUNCTION
INTERIOR See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
HYDRAULICS	
MAST Cylinder	<u>FAIR</u> · Attn
TILT Cylinder	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。