

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/3	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300T00060377			STAMP	HCM1P300T00060377
HR METER	6019	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	450G PADS		

ENGINE : MODEL	4LE2	S/N	
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER) )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5
COMMENT	
アタッチメント: 回転式フォークグラブ	
ATTACHMENT: ROTATABLE FORK GRAB	
MAKE: HITACHI S-FG18RT-6-U2098	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。