

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |        |       |        |
|-----------------|----------------------------------------|------|--------|-------|--------|
| INSPECTION DATE | 2024/4/4                               | MAKE | KUBOTA | MODEL | U-30-5 |
| SERIAL          | 73251                                  |      | STAMP  | 73251 |        |
| HR METER        | 3017                                   | HR   | YEAR   | YR    |        |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE   | 300R  |        |

|                                  |                               |      |                            |
|----------------------------------|-------------------------------|------|----------------------------|
| <b>ENGINE : MODEL</b>            |                               | S/N  | BS1164                     |
| Oil leakage                      | FAIR                          | Attn |                            |
| Blow-By                          | FAIR                          | Attn | A LITTLE · MIDDLE · SEVERE |
| Sound                            | FAIR                          | Attn |                            |
| Oil                              | FAIR                          | Attn |                            |
| Exhaust Color                    | FAIR                          | Attn |                            |
| US EPA                           | YES                           | NO   |                            |
| <b>MAIN PUMP</b>                 |                               |      |                            |
| Sound                            | FAIR                          | Attn |                            |
| Oil leakage                      | FAIR                          | Attn |                            |
| Power                            | FAIR                          | Attn |                            |
| <b>COOLING SYSTEM</b>            |                               |      |                            |
| Radiator                         | FAIR                          | Attn |                            |
| Oil Cooler                       | FAIR                          | Attn |                            |
| <b>OPERATING SYSTEM</b>          |                               |      |                            |
| Swing                            | FAIR                          | Attn | ガタあり SWING: LOOSE          |
| Travel                           | FAIR                          | Attn |                            |
| <b>INTERIOR See Photos. 写真参照</b> |                               |      |                            |
| Operator's Seat                  | FAIR                          | Attn |                            |
| Inside Cover                     | FAIR                          | Attn |                            |
| Glasses                          | FAIR                          | Attn |                            |
| AirCon                           | A/C · H/C · H only · C only · | None |                            |
| <b>BOOM / ARM / BKT</b>          |                               |      |                            |
| Boom                             | FAIR                          | Attn |                            |
| Boom Cylinder                    | FAIR                          | Attn |                            |
| Arm                              | FAIR                          | Attn |                            |
| Arm Cylinder                     | FAIR                          | Attn |                            |
| BKT                              | FAIR                          | Attn | ピンガタあり PIN: LOOSE          |
| BKT Cylinder                     | FAIR                          | Attn |                            |

|                                                                      |                                             |
|----------------------------------------------------------------------|---------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                             |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                                           |
| <b>COMMENT</b>                                                       |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| BKT                                                                  | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG · WRIST                                |
| Multi                                                                | MULTI · 2 · NO                              |
| ARM-CRANE                                                            | YES · NO                                    |
| BLADE                                                                | YES · NO                                    |
| OFFSET                                                               | YES · NO                                    |
| OFFSET Cylinder                                                      | FAIR · Attn                                 |
| Piping                                                               | YES · NO Breaker only · Multi               |
| <b>COMMENT</b>                                                       |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4                                           |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。