

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/4/4	MAKE	KOBELCO	MODEL	SK38UR
SERIAL	PQ02-00264		STAMP	PQ02-00264	
HR METER	4108	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300R	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · Attn 破れあり CUT
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。