

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/4/4	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320EJSXE03439		STAMP	CAT0320EJSXE03439	
HR METER	5139 / 5143	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL C6.6 S/N C8N37066		
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Blow-By	<input checked="" type="radio"/> FAIR	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil	<input checked="" type="radio"/> FAIR	Attn
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn
US EPA	YES	<input checked="" type="radio"/> NO
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Power	<input checked="" type="radio"/> FAIR	Attn
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR	Attn
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR	Attn
Travel	<input checked="" type="radio"/> FAIR	Attn
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn
Inside Cover	<input checked="" type="radio"/> FAIR	Attn
Glasses	<input checked="" type="radio"/> FAIR	Attn
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR	Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn
Arm	<input checked="" type="radio"/> FAIR	Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn
BKT	<input checked="" type="radio"/> FAIR	Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
COMMENT	
E/G関連異常表示あり WARNING DISPLAY FOR ENGINE	
※香港より積み戻し機械(海外未使用)	
※SHIP BACK UNIT FROM HONG KONG (UNUSED OVERSEAS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。