

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/4	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DCFBJ01545		STAMP	CAT0312DCFBJ01545	
HR METER	13150 / 13160	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	700G		

<b>ENGINE : MODEL</b>		S/N	JKH12318
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
<b>MAIN PUMP</b>			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
<b>COOLING SYSTEM</b>			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
<b>OPERATING SYSTEM</b>			
Swing	FAIR	Attn	
Travel	FAIR	Attn	
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	FAIR	Attn	破れあり TOO MUCH WORN
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	*1
AirCon	A/C	H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	*2
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING
BKT	FAIR	Attn	*3
BKT Cylinder	FAIR	Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
左走行モーター油漏れ大(オークション後修理予定)	
LEFT TRAVEL MOTOR: SEVERE OIL LEAKING	
(REPAIRING AFTER THE AUCTION)	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO *4
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
<b>COMMENT</b>	
A/C効かない A/C: MALFUNCTION	
*1 右側アクリル板補修あり RIGHT SIDE GLASS: ACRYLIC BOARD	
*2 左油漏れ大(オークション後修理予定)	
*2 LEFT CYLINDER: SEVERE OIL LEAKING (REPAIRING AFTER THE AUCTION)	
*3 ツースガタ大、バケットピンガタ大 TEETH & PIN: MUCH LOOSE	
*4 バケット巻き込み不可 UNABLE TO ROLL UP THE BUCKET	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。