

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2024/4/4	MAKE	KOMATSU	MODEL	D61PX-23
SERIAL	31841		STAMP	KMT0D120KFA031841	
HR METER	1885	HR	SHOE	860LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">ENGINE : MODEL</td> <td style="width: 70%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Blow-By</td> <td>FAIR · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil</td> <td>FAIR · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR · Attn</td> </tr> <tr> <td>US EPA</td> <td>YES · NO</td> </tr> <tr> <td colspan="2"><b>OPERATION PUMP</b></td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Power</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2"><b>COOLING SYSTEM</b></td> </tr> <tr> <td>Radiator</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2"><b>TRANSMISSION &amp; TRAVEL</b></td> </tr> <tr> <td>T/M TYPE</td> <td>PS · DD DIFF. STEERING YES · NO</td> </tr> <tr> <td>Transmission</td> <td>FAIR · Attn</td> </tr> <tr> <td>Travel</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2"><b>INTERIOR See Photos. 写真参照</b></td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR · Attn</td> </tr> <tr> <td>Inside Cover</td> <td>FAIR · Attn</td> </tr> <tr> <td>Glasses</td> <td>FAIR · Attn</td> </tr> <tr> <td>AirCon</td> <td>A/C · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2"><b>BLADE &amp; CYLINDERS</b></td> </tr> <tr> <td>BLADE</td> <td>FAIR · Attn 固定ピン欠 SOME LOCK PINS: MISSING</td> </tr> <tr> <td>CYLD.(R)</td> <td>FAIR · Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td>FAIR · Attn</td> </tr> <tr> <td>TILT CYLD</td> <td>FAIR · Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	FAIR · Attn	Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE	Sound	FAIR · Attn	Oil	FAIR · Attn	Exhaust Color	FAIR · Attn	US EPA	YES · NO	<b>OPERATION PUMP</b>		Sound	FAIR · Attn	Oil leakage	FAIR · Attn	Power	FAIR · Attn	<b>COOLING SYSTEM</b>		Radiator	FAIR · Attn	Oil Cooler	FAIR · Attn	<b>TRANSMISSION &amp; TRAVEL</b>		T/M TYPE	PS · DD DIFF. STEERING YES · NO	Transmission	FAIR · Attn	Travel	FAIR · Attn	<b>INTERIOR See Photos. 写真参照</b>		Operator's Seat	FAIR · Attn	Inside Cover	FAIR · Attn	Glasses	FAIR · Attn	AirCon	A/C · H/C · H only · C only · None	<b>BLADE &amp; CYLINDERS</b>		BLADE	FAIR · Attn 固定ピン欠 SOME LOCK PINS: MISSING	CYLD.(R)	FAIR · Attn	CYLD.(L)	FAIR · Attn	TILT CYLD	FAIR · Attn	ANGLE CYLD	FAIR · Attn	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2"><b>UNDERCARRIAGE See Photos. 写真参照</b></td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">4</td> </tr> <tr> <td colspan="2"><b>COMMENT</b></td> </tr> <tr> <td colspan="2" style="height: 100px;"> </td> </tr> <tr> <td>Ripper</td> <td>MULTI · S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR · Attn</td> </tr> <tr> <td>EQUALIZER BAR</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2"><b>COMMENT</b></td> </tr> <tr> <td colspan="2" style="height: 100px;"> </td> </tr> <tr> <td>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">4</td> </tr> </table>	<b>UNDERCARRIAGE See Photos. 写真参照</b>		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	<b>COMMENT</b>				Ripper	MULTI · S/S Shanks PCS	Ripper CYLD.	FAIR · Attn	EQUALIZER BAR	FAIR · Attn	<b>COMMENT</b>				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
ENGINE : MODEL	S/N																																																																														
Oil leakage	FAIR · Attn																																																																														
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE																																																																														
Sound	FAIR · Attn																																																																														
Oil	FAIR · Attn																																																																														
Exhaust Color	FAIR · Attn																																																																														
US EPA	YES · NO																																																																														
<b>OPERATION PUMP</b>																																																																															
Sound	FAIR · Attn																																																																														
Oil leakage	FAIR · Attn																																																																														
Power	FAIR · Attn																																																																														
<b>COOLING SYSTEM</b>																																																																															
Radiator	FAIR · Attn																																																																														
Oil Cooler	FAIR · Attn																																																																														
<b>TRANSMISSION &amp; TRAVEL</b>																																																																															
T/M TYPE	PS · DD DIFF. STEERING YES · NO																																																																														
Transmission	FAIR · Attn																																																																														
Travel	FAIR · Attn																																																																														
<b>INTERIOR See Photos. 写真参照</b>																																																																															
Operator's Seat	FAIR · Attn																																																																														
Inside Cover	FAIR · Attn																																																																														
Glasses	FAIR · Attn																																																																														
AirCon	A/C · H/C · H only · C only · None																																																																														
<b>BLADE &amp; CYLINDERS</b>																																																																															
BLADE	FAIR · Attn 固定ピン欠 SOME LOCK PINS: MISSING																																																																														
CYLD.(R)	FAIR · Attn																																																																														
CYLD.(L)	FAIR · Attn																																																																														
TILT CYLD	FAIR · Attn																																																																														
ANGLE CYLD	FAIR · Attn																																																																														
<b>UNDERCARRIAGE See Photos. 写真参照</b>																																																																															
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																														
<b>COMMENT</b>																																																																															
Ripper	MULTI · S/S Shanks PCS																																																																														
Ripper CYLD.	FAIR · Attn																																																																														
EQUALIZER BAR	FAIR · Attn																																																																														
<b>COMMENT</b>																																																																															
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																														

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。