

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2024/4/4	MAKE	CAT	MODEL	D6R
SERIAL	CAT00D6RCBPZ00603		STAMP	CAT00D6RCBPZ00603	
HR METER	16567	HR	SHOE	1000LGP	YEAR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;"><b>ENGINE : MODEL</b></td> <td style="width: 70%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Blow-By</td> <td>(FAIR) · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Oil</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>US EPA</td> <td>YES · (NO)</td> </tr> <tr> <td colspan="2"><b>OPERATION PUMP</b></td> </tr> <tr> <td>Sound</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Power</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2"><b>COOLING SYSTEM</b></td> </tr> <tr> <td>Radiator</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2"><b>TRANSMISSION &amp; TRAVEL</b></td> </tr> <tr> <td>T/M TYPE</td> <td>(PS) · DD DIFF. STEERING (YES) · NO</td> </tr> <tr> <td>Transmission</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Travel</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2"><b>INTERIOR See Photos. 写真参照</b></td> </tr> <tr> <td>Operator's Seat</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Inside Cover</td> <td>(FAIR) · (Attn) 天井剥がれあり INSIDE COVER OF CEILING: PEELED</td> </tr> <tr> <td>Glasses</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>AirCon</td> <td>(A/C) · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2"><b>BLADE &amp; CYLINDERS</b></td> </tr> <tr> <td>BLADE</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>CYLD.(R)</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>TILT CYLD</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> </tr> </table>	<b>ENGINE : MODEL</b>	S/N	Oil leakage	(FAIR) · Attn	Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE	Sound	(FAIR) · Attn	Oil	(FAIR) · Attn	Exhaust Color	(FAIR) · Attn	US EPA	YES · (NO)	<b>OPERATION PUMP</b>		Sound	(FAIR) · Attn	Oil leakage	(FAIR) · Attn	Power	(FAIR) · Attn	<b>COOLING SYSTEM</b>		Radiator	(FAIR) · Attn	Oil Cooler	(FAIR) · Attn	<b>TRANSMISSION &amp; TRAVEL</b>		T/M TYPE	(PS) · DD DIFF. STEERING (YES) · NO	Transmission	(FAIR) · Attn	Travel	(FAIR) · Attn	<b>INTERIOR See Photos. 写真参照</b>		Operator's Seat	(FAIR) · Attn	Inside Cover	(FAIR) · (Attn) 天井剥がれあり INSIDE COVER OF CEILING: PEELED	Glasses	(FAIR) · Attn	AirCon	(A/C) · H/C · H only · C only · None	<b>BLADE &amp; CYLINDERS</b>		BLADE	(FAIR) · Attn	CYLD.(R)	(FAIR) · Attn	CYLD.(L)	(FAIR) · Attn	TILT CYLD	(FAIR) · Attn	ANGLE CYLD	FAIR · Attn	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2"><b>UNDERCARRIAGE See Photos. 写真参照</b></td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">3</td> </tr> <tr> <td colspan="2"><b>COMMENT</b></td> </tr> <tr> <td colspan="2" style="height: 100px;"> </td> </tr> <tr> <td>Ripper</td> <td>MULTI · S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>EQUALIZER BAR</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2"><b>COMMENT</b></td> </tr> <tr> <td colspan="2">! マーク点減あり WARNING LAMP: BLINKED</td> </tr> <tr> <td colspan="2" style="height: 100px;"> </td> </tr> <tr> <td>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">4</td> </tr> </table>	<b>UNDERCARRIAGE See Photos. 写真参照</b>		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	<b>COMMENT</b>				Ripper	MULTI · S/S Shanks PCS	Ripper CYLD.	(FAIR) · Attn	EQUALIZER BAR	(FAIR) · Attn	<b>COMMENT</b>		! マーク点減あり WARNING LAMP: BLINKED				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>ENGINE : MODEL</b>	S/N																																																																																
Oil leakage	(FAIR) · Attn																																																																																
Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE																																																																																
Sound	(FAIR) · Attn																																																																																
Oil	(FAIR) · Attn																																																																																
Exhaust Color	(FAIR) · Attn																																																																																
US EPA	YES · (NO)																																																																																
<b>OPERATION PUMP</b>																																																																																	
Sound	(FAIR) · Attn																																																																																
Oil leakage	(FAIR) · Attn																																																																																
Power	(FAIR) · Attn																																																																																
<b>COOLING SYSTEM</b>																																																																																	
Radiator	(FAIR) · Attn																																																																																
Oil Cooler	(FAIR) · Attn																																																																																
<b>TRANSMISSION &amp; TRAVEL</b>																																																																																	
T/M TYPE	(PS) · DD DIFF. STEERING (YES) · NO																																																																																
Transmission	(FAIR) · Attn																																																																																
Travel	(FAIR) · Attn																																																																																
<b>INTERIOR See Photos. 写真参照</b>																																																																																	
Operator's Seat	(FAIR) · Attn																																																																																
Inside Cover	(FAIR) · (Attn) 天井剥がれあり INSIDE COVER OF CEILING: PEELED																																																																																
Glasses	(FAIR) · Attn																																																																																
AirCon	(A/C) · H/C · H only · C only · None																																																																																
<b>BLADE &amp; CYLINDERS</b>																																																																																	
BLADE	(FAIR) · Attn																																																																																
CYLD.(R)	(FAIR) · Attn																																																																																
CYLD.(L)	(FAIR) · Attn																																																																																
TILT CYLD	(FAIR) · Attn																																																																																
ANGLE CYLD	FAIR · Attn																																																																																
<b>UNDERCARRIAGE See Photos. 写真参照</b>																																																																																	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																
<b>COMMENT</b>																																																																																	
Ripper	MULTI · S/S Shanks PCS																																																																																
Ripper CYLD.	(FAIR) · Attn																																																																																
EQUALIZER BAR	(FAIR) · Attn																																																																																
<b>COMMENT</b>																																																																																	
! マーク点減あり WARNING LAMP: BLINKED																																																																																	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																																

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。