

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/5	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300C00062748		STAMP	HCM1P300C00062748	
HR METER	5413	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G	

<b>ENGINE : MODEL</b> 4LE2 <b>S/N</b> 283697	<b>UNDERCARRIAGE :</b> See Photos. 写真参照
Oil leakage <input checked="" type="radio"/> FAIR · Attn	<b>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> 3
Blow-By <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE	<b>COMMENT</b>
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA <input checked="" type="radio"/> YES · NO	
<b>MAIN PUMP</b>	BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )
Sound <input checked="" type="radio"/> FAIR · Attn	Lever LONG · <input checked="" type="radio"/> WRIST
Oil leakage <input checked="" type="radio"/> FAIR · Attn	Multi <input checked="" type="radio"/> MULTI · 2 · NO
Power <input checked="" type="radio"/> FAIR · Attn	ARM-CRANE <input checked="" type="radio"/> YES · NO
<b>COOLING SYSTEM</b>	BLADE <input checked="" type="radio"/> YES · NO
Radiator <input checked="" type="radio"/> FAIR · Attn	OFFSET YES · <input checked="" type="radio"/> NO
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	OFFSET Cylinder FAIR · Attn
<b>OPERATING SYSTEM</b>	Piping <input checked="" type="radio"/> YES · NO <input checked="" type="radio"/> Breaker only · Multi
Swing <input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn ガタあり SWING: LOOSE	<b>COMMENT</b>
Travel <input checked="" type="radio"/> FAIR · Attn	
<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	
Inside Cover <input checked="" type="radio"/> FAIR · Attn	
Glasses <input checked="" type="radio"/> FAIR · Attn	
AirCon <input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>	
Boom <input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder <input checked="" type="radio"/> FAIR · Attn	
Arm <input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder <input checked="" type="radio"/> FAIR · Attn	
BKT <input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder <input checked="" type="radio"/> FAIR · Attn	<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。