INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/4/5	MAKE	HITACHI	MODEL	LX30-7
SERIAL	HFK4E200A00003930		STAMP	F37-03930	
HR METER	4865 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / (CNP) / NONE		TIRE SIZE	15.5/60-18	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	にじみあり OIL OOZING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR)・ Attn	破れあり CUTS
Inside Cover	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・(None)	
FRONT & CYLINDERS		
Arm	(FAIR)・ Attn	
Bell crank	(FAIR)・ Attn	
Bucket	(FAIR)・ Attn	
Articulate	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		
COMMENT			
STEERING TYPE	WHEEL STEERING / (COMMAND STEERING) / LEVER STEERING		
RIDE CONTROL	YES ・(NO)		
ATTACHMENTS			
STD BKT	(YES)・ OTHER		
BLADE	YES ・(NO)	Piping for Tilt	YES ・(NO)
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。