

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/4/5	MAKE	KUBOTA	MODEL	RX-306E
SERIAL	24691		STAMP	24691	
HR METER	1452	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N	7JTA551
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES	<input checked="" type="radio"/> NO	
MAIN PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
OPERATING SYSTEM			
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only · <input type="radio"/> C only · None
BOOM / ARM / BKT			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
BKT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	<input checked="" type="radio"/> YES · NO
OFFSET Cylinder	<input checked="" type="radio"/> FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。