# INSPECTION SHEET 検品書
## ROLLER ローラー

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2024/4/4 | MAKE | DYNAPAC | MODEL | CS12Ⅲ |
| SERIAL | 1245 | | | STAMP | CS12-1245 |
| HR METER | E1372 HR | Odometer | – km | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / (CNP) / NONE | | | TIRE SIZE | – |

| ENGINE : MODEL | | S/N |
|---|---|---|
| Oil leakage | (FAIR) · Attn | |
| Blow-By | (FAIR) · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | (FAIR) · Attn | |
| Oil | (FAIR) · Attn | |
| Exhaust Color | (FAIR) · Attn | |
| US EPA | YES · (NO) | |
| **OPERATION PUMP** | | |
| Sound | (FAIR) · Attn | |
| Oil leakage | FAIR · (Attn) | 油漏れ小 OIL LEAKING |
| Power | (FAIR) · Attn | |
| **COOLING SYSTEM** | | |
| Radiator | (FAIR) · Attn | |
| Oil Cooler | (FAIR) · Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | (PS) · DD | |
| Transmission | (FAIR) · Attn | |
| Travel | (FAIR) · Attn | *1 |
| FOOT BRAKE | FAIR · Attn | |
| PARKING BRAKE | FAIR · (Attn) | あまり効かない BRAKE: MUCH LOOSE |
| **INTERIOR** | **See Photos. 写真参照** | |
| Operator's Seat | (FAIR) · Attn | |
| Inside Cover | FAIR · Attn | |
| Glasses | FAIR · Attn | |
| AirCon | A/C · H/C · H only · C only · (None) | |
| **OTHERS** | | |
| Vibratory | FAIR · Attn | |
| Watering | FAIR · (Attn) | *2 |
| Articulate | FAIR · (Attn) | シリンダー油漏れ小 CYLINDERS: OIL LEAKING |

| UNDERCARRIAGE : See Photos. 写真参照 | |
|---|---|
| **RUST**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 |
| **COMMENT** | |
| 燃料計故障あり FUEL GAUGE: MALFUNCTION | |
| 底板油漏れ小 BOTTOM: OIL LEAKING | |
| HRメーターストップ HR METER: STOPPED | |
| *1 高速/低速レバー固着あり HI/LO SWITCH LEVER: STUCK | |
| *2 ポンプは動いているが水出ない NOT WATERING (PUMP: WORKING) | |
| **RUST of BODY**(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。