

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/5	MAKE	KATO	MODEL	KR-25H-V3
SERIAL No.	PLATE : 3410434	STAMP :		KR257-0484	
HR METER	24531	HR	Odometer	73412	km
TIRE SIZE	385/95R25	YEAR	YR		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input checked="" type="radio"/> SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	排気漏れ大 MUCH EXHAUST LEAKING

<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	

<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	

<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	

<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD

<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Inside Cover	FAIR <input checked="" type="radio"/> Attn	腐食あり CORRODED
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C	H only · C only · None

<b>COMMENT</b>		

<b>BOOM</b>		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn	
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn	
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn	
JIB	YES <input checked="" type="radio"/> NO	
JIB TYPE	STD <input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO	
HOOK	25t, BALL	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

<b>COMMENT</b>		

<b>OUTRIGGERS</b>		
OUTRIGGERS	X <input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn	

<b>COMMENT</b>		
*1 下周り、E/Gヘッドカバー油漏れあり BOTTOM & HEAD COVER: OIL LEAKING		

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。