

**INSPECTION SHEET 検品書**  
**FORK LIFT フォークリフト**

INSPECTION DATE	2024/4/8	MAKE	MITSUBISHI	MODEL	FD40
SERIAL	F19-00768			STAMP	NOT FOUND
HR METER	818	HR	Odometer	-	km YEAR YR
CAB/CNP	CAB / <b>CNP</b> / NONE	TIRE SIZE		F: 7.50-16 R: 7.00-12	
MAX LIFTING HEIGHT	1.55	m	VIEW	<b>MONO</b>	FORK LENGTH - mm
FORK SPEC	マニプレータ MANIPULATOR				

ENGINE : MODEL	S/N
Oil leakage	<b>FAIR</b> · Attn
Blow-By	<b>FAIR</b> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<b>FAIR</b> · Attn
Oil	<b>FAIR</b> · Attn
Exhaust Color	<b>FAIR</b> · Attn
US EPA	YES · <b>NO</b>
<b>OPERATION PUMP</b>	
Sound	<b>FAIR</b> · Attn
Oil leakage	<b>FAIR</b> · Attn
Power	<b>FAIR</b> · Attn
<b>COOLING SYSTEM</b>	
Radiator	<b>FAIR</b> · Attn
Oil Cooler	<b>FAIR</b> · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	<b>PS</b> · DD
Transmission	<b>FAIR</b> · Attn
Travel	<b>FAIR</b> · Attn
FOOT BRAKE	<b>FAIR</b> · Attn
PARKING BRAKE	<b>FAIR</b> · <b>Attn</b> 不良 MALFUNCTION
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	<b>FAIR</b> · Attn 破れあり CUTS
Inside Cover	<b>FAIR</b> · Attn
Glasses	<b>FAIR</b> · Attn
AirCon	A/C · H/C · H only · C only · <b>None</b>
<b>HYDRAULICS</b>	
MAST Cylinder	<b>FAIR</b> · <b>Attn</b> 油漏れあり OIL LEAKING
TILT Cylinder	<b>FAIR</b> · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
チャージランプ点灯あり CHARGE LAMP: ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。