

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/4/8	MAKE	TCM	MODEL	FHD150Z
SERIAL	NO PLATE			STAMP	F60-00500
HR METER	5361	HR	Odometer	-	km YEAR YR
CAB/CNP	<input checked="checked" type="radio"/> CAB	/	<input type="radio"/> CNP	/	<input type="radio"/> NONE
TIRE SIZE	12.00-24				
MAX LIFTING HEIGHT	3.0	m	<input checked="checked" type="radio"/> VIEW	MONO	FORK LENGTH 1200 mm
FORK SPEC	ヒンジドフォーク HINGED FORK				

ENGINE : MODEL	S/N
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn
Blow-By	<input type="radio"/> FAIR · <input checked="checked" type="radio"/> A LITTLE <input checked="checked" type="radio"/> MIDDLE · <input type="radio"/> SEVERE
Sound	<input checked="checked" type="radio"/> FAIR · Attn
Oil	<input checked="checked" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="checked" type="radio"/> FAIR · Attn
US EPA	YES · <input checked="checked" type="radio"/> NO
OPERATION PUMP	
Sound	<input checked="checked" type="radio"/> FAIR · Attn
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn
Power	<input checked="checked" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="checked" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="checked" type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<input checked="checked" type="radio"/> PS · <input type="radio"/> DD
Transmission	<input checked="checked" type="radio"/> FAIR · Attn
Travel	<input checked="checked" type="radio"/> FAIR · Attn
FOOT BRAKE	<input checked="checked" type="radio"/> FAIR · Attn
PARKING BRAKE	<input checked="checked" type="radio"/> FAIR · <input checked="checked" type="radio"/> 不良 MALFUNCTION
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="checked" type="radio"/> FAIR · Attn 破れあり HUGE CUTS
Inside Cover	<input checked="checked" type="radio"/> FAIR · Attn
Glasses	<input checked="checked" type="radio"/> FAIR · Attn
AirCon	<input checked="checked" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None
HYDRAULICS	
MAST Cylinder	<input checked="checked" type="radio"/> FAIR · Attn
TILT Cylinder	<input checked="checked" type="radio"/> FAIR · <input checked="checked" type="radio"/> 右チルト油漏れあり RIGHT CYLINDER: OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT 後付けHRメーター: 2649HR RETROFITTED HR METER: 2649HR	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。