

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/4/8	MAKE	MITSUBISHI	MODEL	BD2H
SERIAL	HB650020		STAMP	2B650020	
HR METER	2918	HR	SHOE	500LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N	20838
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · DD	DIFF. STEERING	YES · NO
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR · Attn	損傷あり DAMAGED	
Inside Cover	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BLADE & CYLINDERS			
BLADE	FAIR · Attn		
CYLD.(R)	FAIR · Attn	*1	
CYLD.(L)	FAIR · Attn	*1	
TILT CYLD	FAIR · Attn		
ANGLE CYLD	FAIR · Attn	*2	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
EQUALIZER BAR	FAIR · Attn		
COMMENT			
右レバーS/W破損あり RIGHT OPERATION LEVER SWITCH: BROKEN			
*1 油漏れ大(オークション後修理予定)			
*1 SEVERE OIL LEAKING (REPAIRING AFTER THE AUCTION)			
*2 右油漏れ大(オークション後修理予定)			
*2 RIGHT CYLINDER: SEVERE OIL LEAKING			
(REPAIRING AFTER THE AUCTION)			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。