

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/10	MAKE	KATO	MODEL	KRM-25H
SERIAL No.	PLATE :	0611062		STAMP :	KR248-1062
HR METER	21360	HR	Odometer	74155	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL 6D16 S/N

Oil leakage	FAIR	<input checked="" type="radio"/> Attn	E/G下周りにじみあり BOTTOM: OIL OOZING
Blow-By	FAIR	<input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	<input type="radio"/> Attn	
Oil	FAIR	<input type="radio"/> Attn	
Exhaust Color	FAIR	<input type="radio"/> Attn	

OPERATION PUMP

Sound	FAIR	<input type="radio"/> Attn	
Oil leakage	FAIR	<input type="radio"/> Attn	
Power	FAIR	<input type="radio"/> Attn	

COOLING SYSTEM

Radiator	FAIR	<input type="radio"/> Attn	
Oil Cooler	FAIR	<input type="radio"/> Attn	

OPERATING SYSTEM

Computer	OK	<input type="radio"/> NG	
Swing	FAIR	<input type="radio"/> Attn	
Travel	FAIR	<input type="radio"/> Attn	

TRANSMISSION

Transmission	FAIR	<input type="radio"/> Attn	
No. OF GEARS	4	GEARS	
No. of DRIVE WHEELS	4	WD	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	<input type="radio"/> Attn	
Inside Cover	FAIR	<input type="radio"/> Attn	
Glasses	FAIR	<input type="radio"/> Attn	
AirCon	A/C	H/C · H only · C only · None	

COMMENT

--

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input type="radio"/> Attn	
DERRICKING CYL.	FAIR	<input checked="" type="radio"/> Attn	ロッド傷あり ROD: SCRATCHED
EXTENSION CYL.	FAIR	<input type="radio"/> Attn	
JIB	YES	<input type="radio"/> NO	
JIB TYPE	STD	<input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	YES	<input type="radio"/> NO	
HOOK	25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

--

OUTRIGGERS

OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR	<input checked="" type="radio"/> Attn	*1

COMMENT

補巻ウインチモーター下周りにじみあり BOTTOM OF AUXILIARY HOISTING WINCH MOTOR: OIL OOZING 左右Fウインカーレンズ割れあり FRONT BLINKER COVERS: BROKEN 左ミラー割れあり LEFT OUTER REAR-VIEW MIRROR: MUCH CRACKED ブーム4~6段目非常にて格納 4th TO 6th BOOM: NEED TO OPERATE WITH THE EMERGENCY MODE TO SHRINK *1 左Fロッド傷あり FRONT LEFT VERTICAL CYLINDER ROD: SCRATCHED

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。