INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/10	MAKE	KOBELCO	MODEL	RK250-6
SERIAL No.	PLATE : EZ08-10230			STAMP :	EZ08-10230
HR METER	34359 HR			Odometer	96890 km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Computer	OK・NG	
Swing	FAIR・Attn	
Travel	FAIR・Attn	
TRANSMISSION		
Transmission	FAIR・Attn	
No. OF GEARS	3 GEARS	
No, of DRIVE WHEELS	4 WD	
INTERIOR	See Photos. 写真参照	
Operator's Seat	FAIR・Attn	破れあり CUTS
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	

COMMENT

CAB腐食あり CAB: CORRODED

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR・Attn	
DERRICKING CYL.	FAIR・Attn	
EXTENSION CYL.	FAIR・Attn	にじみあり OIL OOZING
JIB	YES・NO	
JIB TYPE	STD・PWR	
MAIN & SUB WIRE	YES・NO	
HOOK	25t, BALL	
UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

COMMENT

OUTRIGGERS		
OUTRIGGERS	X・H	
OUTRIGGERS COND.	FAIR・Attn	*1

COMMENT

*1 縦シリンダー4本にじみあり VERTICAL CYLINDERS: OIL OOZING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。