

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/10	MAKE	TADANO	MODEL	TR-500M-3
SERIAL No.	PLATE :	582366	STAMP :	TR551-0919	
HR METER	6316	HR	Odometer	107827	km
TIRE SIZE	505/95R25	YEAR	YR		

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn 内部サビあり INSIDE: RUSTY
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION	
Transmission	<input checked="" type="radio"/> FAIR · Attn
No. OF GEARS	4 GEARS
No. of DRIVE WHEELS	4 WD
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
COMMENT	
CABへコミあり CAB: DENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn *1
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn にじみあり OIL OOZING
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	25t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
リヤステ切替えS/W不良 REAR STEERING SWITCH: MALFUNCTION	
OUTRIGGERS	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn *2
COMMENT	
メインフックなし NO MAIN HOOK	
マフラーテールパイプ脱落あり MUFFLER END PIPE: MISSING	
ロータリー油漏れあり ROTARY: OIL LEAKING	
ラジエータ周り水漏れ跡あり AROUND RADIATOR: WATER LEAKING	
伸縮ワイヤーたるみあり	
WIRES: SLACKENING WHEN BOOM SHRINKING	
(BOOM: NEED TO SHRINK SLOWLY)	
*1 1本油漏れあり SOME CYLINDER: OIL LEAKING	
*2 F縦シリンダーにじみあり FRONT VERTICAL CYLINDERS: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。