

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/10	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB3778		STAMP : TR256-0496		
HR METER	14198	HR	Odometer	50637	km
TIRE SIZE	385/95R25		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	穴あり HOLE
Inside Cover	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/>	H/C · H only · C only · None
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn
JIB	YES <input checked="" type="radio"/> NO
JIB TYPE	STD <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO
HOOK	25t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X <input checked="" type="radio"/> H
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn
<b>COMMENT</b>	
*1 E/G下周り、E/Gヘッド油漏れあり	
*1 BOTTOM & CYLINDER HEAD: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。