

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2024/4/11	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE :	5910188		STAMP :	KR130-0188
HR METER	20390	HR	Odometer	146341	km
TIRE SIZE	275/80R22.5		YEAR	YR	

**ENGINE : MODEL W04D S/N**

Oil leakage	FAIR	<input checked="" type="radio"/> Attn	*1
Blow-By	FAIR	<input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	FAIR	<input type="radio"/> Attn	
Oil	FAIR	<input type="radio"/> Attn	
Exhaust Color	FAIR	<input type="radio"/> Attn	

**OPERATION PUMP**

Sound	FAIR	<input type="radio"/> Attn	
Oil leakage	FAIR	<input type="radio"/> Attn	
Power	FAIR	<input type="radio"/> Attn	

**COOLING SYSTEM**

Radiator	FAIR	<input type="radio"/> Attn	
Oil Cooler	FAIR	<input type="radio"/> Attn	

**OPERATING SYSTEM**

Computer	OK	<input type="radio"/> NG	
Swing	FAIR	<input type="radio"/> Attn	
Travel	FAIR	<input type="radio"/> Attn	

**TRANSMISSION**

Transmission	FAIR	<input type="radio"/> Attn	
No. OF GEARS	3	GEARS	
No. of DRIVE WHEELS	4	WD	

**INTERIOR See Photos. 写真参照**

Operator's Seat	FAIR	<input type="radio"/> Attn	
Inside Cover	FAIR	<input type="radio"/> Attn	
Glasses	FAIR	<input type="radio"/> Attn	
AirCon	A/C	<input checked="" type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	

**COMMENT**

--

**BOOM**

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input type="radio"/> Attn	
DERRICKING CYL.	FAIR	<input type="radio"/> Attn	
EXTENSION CYL.	FAIR	<input type="radio"/> Attn	
JIB	YES	<input type="radio"/> NO	
JIB TYPE	STD	<input type="radio"/> PWR	
MAIN & SUB WIRE	YES	<input type="radio"/> NO	
HOOK	13t, BALL		

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

**COMMENT**

--

**OUTRIGGERS**

OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR	<input type="radio"/> Attn	

**COMMENT**

過巻装置エラーあり(エラー表示なし、警報が鳴る)
OVERWINDING PREVENTION ERROR (NO ERROR MESSAGE, JUST WARNING SOUNDS)
*1 E/G下周り、E/Gヘッド油漏れあり BOTTOM & CYLINDER HEAD: OIL LEAKING


RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。