INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2023/7/18	CATEGORY	EARTH AUGER (アースオーガ掘進機)				
MAKE	AVOLON			MODEL	AS-2700		
SERIAL	1190			STAMP	NOT FOUND		
HR METER	HR	Odometer	km	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE		TIRE			

ENGINE	MODEL		S/N		
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR ・ Attn	
未確認 NOT CHECKED		

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
COMMENT		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。