

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE	2024/4/12	CATEGORY	CLAMSHELL BUCKET			
MAKE	UNKNOWN			MODEL	UNKNOWN	
SERIAL	-			STAMP	-	
HR METER	-	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE		TIRE	

ENGINE	MODEL	S/N			
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE		Exhaust Color	FAIR ・ Attn
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR ・ Attn	
未確認 OPERATION: NOT CHECKED		

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	
COMMENT		
80φ × 310mm		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。