

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2024/4/12	CATEGORY	CLAMSHELL BUCKET		
MAKE	UNKNOWN		MODEL	UNKNOWN	
SERIAL	-		STAMP	-	
HR METER	-	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	TIRE	

ENGINE	MODEL	S/N
Oil leakage	FAIR · Attn	Oil FAIR · Attn
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE Exhaust Color FAIR · Attn
Sound	FAIR · Attn	EPA YES · NO

CONDITION	FAIR · Attn	
未確認 OPERATION: NOT CHECKED		

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	
COMMENT		
<div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div>		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。