

INSPECTION SHEET 検品書  
OTHER その他

INSPECTION DATE	2024/4/12	CATEGORY	ORANGE PEEL GRAPPLE			
MAKE	UNKNOWN		MODEL	UNKNOWN		
SERIAL	-		STAMP	-		
HR METER	-	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE		TIRE	

ENGINE	MODEL	S/N			
Oil leakage	FAIR · Attn		Oil	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR · Attn	
Sound	FAIR · Attn		EPA	YES · NO	

CONDITION	FAIR · Attn	
未確認 OPERATION: NOT CHECKED		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	
<b>COMMENT</b>		
<div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dashed black; margin-bottom: 5px;"></div>		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。