

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |   |      |         |            |            |
|-----------------|---|------|---------|------------|------------|
| INSPECTION DATE | 2023/3/14                                     | MAKE | KOBELCO | MODEL      | SK320LC-6E |
| SERIAL          | YC07-02863                                    |      | STAMP   | YC07-02863 |            |
| HR METER        | 7360  | HR   | YEAR    | YR         |            |
| CAB/CNP         | ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE |      | SHOE    | 600G       |            |

|                                  |   |                            |
|----------------------------------|---|----------------------------|
| <b>ENGINE : MODEL</b>            |   | <b>S/N</b>                 |
| Oil leakage                      | <u>FAIR</u> · Attn                        |                            |
| Blow-By                          | <u>FAIR</u> · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                            | <u>FAIR</u> · Attn                        |                            |
| Oil                              | <u>FAIR</u> · Attn                        |                            |
| Exhaust Color                    | <u>FAIR</u> · Attn                        |                            |
| US EPA                           | YES · <u>NO</u>                           |                            |
| <b>MAIN PUMP</b>                 |   |                            |
| Sound                            | <u>FAIR</u> · Attn                        |                            |
| Oil leakage                      | <u>FAIR</u> · Attn                        |                            |
| Power                            | <u>FAIR</u> · Attn                        |                            |
| <b>COOLING SYSTEM</b>            |   |                            |
| Radiator                         | <u>FAIR</u> · Attn                        |                            |
| Oil Cooler                       | <u>FAIR</u> · Attn                        |                            |
| <b>OPERATING SYSTEM</b>          |   |                            |
| Swing                            | <u>FAIR</u> · Attn                        |                            |
| Travel                           | <u>FAIR</u> · Attn                        |                            |
| <b>INTERIOR See Photos. 写真参照</b> |   |                            |
| Operator's Seat                  | <u>FAIR</u> · Attn                        |                            |
| Inside Cover                     | <u>FAIR</u> · Attn                        |                            |
| Glasses                          | <u>FAIR</u> · Attn                        |                            |
| AirCon                           | <u>A/C</u> · H/C · H only · C only · None |                            |
| <b>BOOM / ARM / BKT</b>          |   |                            |
| Boom                             | <u>FAIR</u> · Attn                        | 2ピースブーム 2 PIECE BOOM       |
| Boom Cylinder                    | <u>FAIR</u> · Attn                        |                            |
| Arm                              | <u>FAIR</u> · Attn                        |                            |
| Arm Cylinder                     | <u>FAIR</u> · Attn                        |                            |
| BKT                              | <u>FAIR</u> · Attn                        |                            |
| BKT Cylinder                     | <u>FAIR</u> · Attn                        |                            |

|   |  |
|---|--|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                               |  |
| RUSTS (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3  |
| <b>COMMENT</b>  |  |
|   |  |
| BKT   | <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever   | LONG · <u>WRIST</u>                                |
| Multi   | <u>MULTI</u> · 2 · NO                              |
| ARM-CRANE   | YES · <u>NO</u>                                    |
| BLADE   | YES · <u>NO</u>                                    |
| OFFSET  | YES · <u>NO</u>                                    |
| OFFSET Cylinder   | FAIR · Attn  |
| Piping  | <u>YES</u> · NO Breaker only · <u>Multi</u> 5      |
| <b>COMMENT</b>  |  |
| 右後ろレボフレーム変形あり REVOLVING FRAME OF REAR RIGHT: DEFORMED                 |  |
| 付属品: オーガーあり AUGER AS SPARE  |  |
|   |  |
| RUSTS of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。