INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2023/10/26	MAKE	KOMATSU	MODEL	510
SERIAL	12925			STAMP	510-12925
HR METER	7613 HR	Odometer	41834 km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 10PR

ENGINE : MODEL 4D105-3 S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	効き弱い BRAKE: LOOSE
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR・Attn	破れあり CUTS
Inside Cover	FAIR・Attn	汚れあり DIRTY
Glasses	FAIR・Attn	*1
AirCon	A/C・H/C・H only・C only・None	
FRONT & CYLINDERS		
Arm	FAIR・Attn	
Bell crank	FAIR・Attn	
Bucket	FAIR・Attn	シリンダー油漏れあり CYLINDER: OIL LEAKING
Articulate	FAIR・Attn	*2

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES・NO		
ATTACHMENTS			
STD BKT	YES・OTHER		
BLADE	YES・NO	Piping for Tilt	YES・NO
COMMENT			

E/Gストップ不良(アクセルペダル手前に引くとストップする)
ENGINE STOPPER: MALFUNCTION
(ABLE TO STOP THE ENGINE BY PULLING THE ACCELERATOR PEDAL)
ラジオ故障 RADIO: MALFUNCTION
*1 F左窓クラックあり FRONT LEFT SIDE GLASS: CRACKED
*2 左シリンダーにじみあり LEFT CYLINDER: OIL OOZING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。