

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/1/12	MAKE	KOMATSU	MODEL	WA100-1
SERIAL	30046		STAMP	W005-30046	
HR METER	11043	HR	Odometer	34012	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	16.9-24 10PR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	E/G周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<input checked="" type="radio"/> PS · DD	
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE	FAIR · <input checked="" type="radio"/> Attn	効き悪い BRAKE: LOOSE
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · <input checked="" type="radio"/> Attn	破れあり HUGE CUTS
Inside Cover	FAIR · <input checked="" type="radio"/> Attn	汚れ大 DIRTY
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None	
FRONT & CYLINDERS		
Arm	<input checked="" type="radio"/> FAIR · Attn	
Bell crank	<input checked="" type="radio"/> FAIR · Attn	
Bucket	<input checked="" type="radio"/> FAIR · Attn	
Articulate	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING	
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
ATTACHMENTS	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt <input checked="" type="radio"/> YES · NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
センターピンガタあり CENTER PIN: LOOSE	
左Fミラー割れあり LEFT OUTER REAR-VIEW MIRROR: CRACKED	
下周り油漏れあり(吸着マットあり)	
BOTTOM: OIL LEAKING (W/ABSORPTION MAT)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。