

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2023/12/11	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300V00062959		STAMP	HCM1P300V00062959	
HR METER	6732	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	450G PADS	

**ENGINE : MODEL** 4LE2 **S/N** 287413

Oil leakage	<u>FAIR</u>	Attn	
Blow-By	<u>FAIR</u>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u>	Attn	
Oil	<u>FAIR</u>	Attn	
Exhaust Color	<u>FAIR</u>	Attn	
US EPA	YES	<u>NO</u>	

**MAIN PUMP**

Sound	<u>FAIR</u>	Attn	
Oil leakage	<u>FAIR</u>	Attn	
Power	<u>FAIR</u>	Attn	

**COOLING SYSTEM**

Radiator	<u>FAIR</u>	Attn	
Oil Cooler	<u>FAIR</u>	Attn	

**OPERATING SYSTEM**

Swing	<u>FAIR</u>	Attn	
Travel	<u>FAIR</u>	Attn	

**INTERIOR See Photos. 写真参照**

Operator's Seat	FAIR	<u>Attn</u>	破れあり CUTS
Inside Cover	<u>FAIR</u>	Attn	
Glasses	<u>FAIR</u>	Attn	
AirCon	<u>A/C</u>	H/C · H only · C only · None	

**BOOM / ARM / BKT**

Boom	<u>FAIR</u>	Attn	
Boom Cylinder	<u>FAIR</u>	Attn	
Arm	<u>FAIR</u>	Attn	
Arm Cylinder	<u>FAIR</u>	Attn	
BKT	<u>FAIR</u>	Attn	
BKT Cylinder	<u>FAIR</u>	Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 3

**COMMENT**

シューリンクコンクリート付着あり TRACK LINKS: CONCRETE STAINS

BKT STD / SLOPE / NARROW / SKELETON / OTHER( )

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

**COMMENT**

**RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。